

June 19, 2014

Mr. Jeff Derouen Executive Director Public Service Commission 211 Sower Boulevard Frankfort, Kentucky 40602

Re: ADMINISTRATIVE CASE NO. 2011-00450

AN INVESTIGATION OF THE RELIABILITY MEASURES OF KENTUCKY'S JURISDICTIONAL ELECTRIC DISTRIBUTION UTILITIES

JUNISDICTIONAL ELECTRIC DISTRIBUTION UTILITIE

Dear Mr. Derouen:

Enclosed is the Electric Distribution Utility Annual Reliability Report for Inter-County Energy Cooperative pursuant to the Public Service Commission Administrative Case No. 2011-00450 dated April 1, 2014.

If you have further questions or comments, please direct those to David Phelps, Vice President-Operations. His direct line is 859-936-7818 or email to davidp@intercountyenergy.net.

Sincerely,


James L. Jacobus President/CEO


Copy To: Mr. Kyle Willard, Director of Engineering, KY Public Service Commission



JUN 23 2014

PUBLIC SERVICE COMMISSION





Administrative Case No. 2011-00450

June 18, 2014

Electric Distribution Utility Annual Reliability Report

- Contact Information
- Report Year
- · Major Event Days
- · System Reliability Information and Results
- Circuit Reporting
- Vegetation Management Plan Review
- Utility Comments

Electric Distribution Uti	lity A	nnual Reliability Report
SECTION 1: CO	NTACT	INFORMATION
UTILITY NAME REPORT PREPARED BY E-MAIL ADDRESS OF PREPARER PHONE NUMBER OF PREPARER	1.1 1.2 1.3 1.4	Inter-County Energy David Pheips davidp@intercountyenergy net 859-236-4561 ext. 7818
SECTION	2: REPC	DRT YEAR
CALENDAR YEAR OF REPORT	2.1	2013
SECTION 3: M	MAJOR	EVENT DAYS
T _{MED}	3.1	12.85091
FIRST DATE USED TO DETERMINE TMED	3.2	Jan. 1, 2008
LAST DATE USED TO DETERMINE TMED	3.3	Dec. 31, 2012
NUMBER OF MED IN REPORT YEAR	3.4	3
NOTE: Per IEEE 1366 T _{MED} should be calculated five years of data are not available, then utilities accumulated.	_	· · · · · · · · · · · · · · · · · · ·
SECTION 4: SYSTEM RELIAB	BILITY IN	IFORMATION AND RESULTS
System-	wide Info	ormation
TOTAL CUSTOMERS 26121		TOTAL CIRCUITS42
Exc	luding N	1ED
5 YEAR AVERAGE SAIDI 107.18 SAIFI 1.29		REPORTING YEAR SAIDI 77.01 SAIFI 0 92

Including MED

5 Y	EAR AVERAGE	REPORTING YEAR
SAIDI	2723.59	SAIDI <u>1</u> 43.27
SAIFI	2.29	SAIFt1.11

Notes:

- All duration indices (SAIDI, CAIDI) are to be reported in units of minutes.
 Reports are due on the first business day of April of each year
 Reports cover the calendar year ending in the December before the reports are due.
- 4) IEEE 1368 (latest version) is used to define SAIDI, SAIFI, CAIDI, and T_{MED}

Section 5: Circuit Reporting 2013

Circuit #1:

1. Substation Name and Number	Ballard (2)
2. Substation Location	Lincoln-Fisher Ford Rd-Lancaster
3. Circuit Name and Number	WellsLanding(2)
4. Circuit Location	
Wells Landing Rd, 0	Old Bridge, Taylor Rd, Old Lexington Rd
5. Total Circuit Length (Miles)	24.16
6. Customer Count	484
7. Date of Last Circuit Trim	Feb-10
8. Outage Cause (% of Total Outage Numbers)	
Animals	5 15.94%
Lightning	74.44%
High Wind	2.46%
Equip. Failure	1.58%
Deteriorated	0.00%
Cars or Trucks	0.00%
Insulation broke	0.61%
Vegetation/Trees	2.46%
Trees Cut Into Line	0 00%
Equipment OL	0.00%
Rain/ Ice	2.52%
Cased by Others	0 00%
9. Circuit 5 Year Average (SAIDI)	45.98212679
10. Reporting Year (SAIDI)	120.8822314
11. Circuit 5 Year Average (SAIFI)	30.32066802
12. Reporting Year (SAIFI)	79.83471074
13. List of Corrective Action, If Any, Taken or To Be Taken	
2014-2017 Work Plan Actions To Be Taken:	None

CI	rcu	iŧ	#2.
~		IIL	W4.

Substation Name and Number	Garrard(13)	
2. Substation Location	Lincoln-Richmond Rd-Lancaster	
3. Circuit Name and Number	Paintlick(1)	
4. Circuit Location		
Lar	noster-Hwy. 52 E, Flatwoord, Hwy. 129	
5. Total Circuit Length (Miles)	72.61	
6. Customer Count	587	
7. Date of Last Circuit Trim	Dec-10	
B. Outage Cause (% of Total Outage Numbers)		
Animals	3.06%	
Lightning	16.78%	
High Wind	60.86%	
Equip. Failure	4.54%	
Deteriorated	10.66%	
Cars or Trucks	0.24%	
Insulation broke	0.00%	
Vegetation/Trees	3.85%	
Trees Cut Into Line	0.00%	
Equipment OL	0.00%	
Rain/ Ice	0.00%	
Cased by Others	0.00%	
9. Circuit 5 Year Average (SAIDI)	64.10608823	
10. Reporting Year (SAIDI)	81.11073253	
11. Circuit 5 Year Average (SAiFI)	55.66960388	
I2. Reporting Year (SAiFI)	85.34923339	
3. List of Corrective Action, If Any, Taken or To Be Taken		
2014-2017 Work Plan Actions To Be Taken:	302 (2016) , 303 (2015), 304 (2016)	
Gooch Pike-Replace 2.9 mile of 1 phase #4 ACSR with 1 phase 1/	0 AAAC.	
Hurt Lane-Convert 3.5 miles of 1 phase distribution from 7.2 to 14.	4 KV.	
Doty Lane-Convert 5.1 miles of 1 phase #4ACSR distribution circu	it to 1 phase 1/0 AAAC.	

Substation Name and Number	Gooch(11)	
2. Substation Location	Lincoln-Rice Ln-Stanford	
3. Circuit Name and Number	CrabOrchard(2)	
4. Circuit Location		
	Copper Creek, Harmons Lick, KY 39	
5. Total Circuit Length (Miles)	90.27	
6. Customer Count	758	
7. Date of Last Circuit Trim	May-12	
8. Outage Cause (% of Total Outage Numbers)		
Animals	2.73%	
Lightning	24.83%	
High Wind	28.95%	
Equip. Failure	5.37%	
Deteriorated	1.36%	
Cars or Trucks	15.53%	
Insulation broke	0.00%	
Vegetation/Trees	18.00%	
Trees Cut Into Line	0.00%	
Equipment OL	1.88%	
Rain/ Ice	1.36%	
Cased by Others	0.00%	
9. Circuit 5 Year Average (SAIDI)	174.1812004	
10. Reporting Year (SAIDI)	33.99868074	
11, Circuit 5 Year Average (SAIFI)	146.8386351	
12. Reporting Year (SAIFI)	200.2638522	
13. List of Corrective Action, If Any, Taken or To Be Taken		
2014-2017 Work Plan Actions To Be Taken:	307 (2015), 310 (2014), 313 (2014)	
Old Hwy 150-Convert 1.8 miles of 1 phase #2ACSR distribution ci	rcuit to 3 phase 1/0 AAAC.	
Pine Grove Rd-Convert 3.34 miles of 1 phase distribution from 7.2		
Deep Well Woods Rd-Convert 5.6 miles of 1 phase distribution from	om 7.2 to <u>14.4</u> KV.	

C	ec.	de	#4
•		316	-

2014-2017 Work Plan Actions To Be Taken:

Substation Name and Number	Gooch(11)	
2. Substation Location	Lincoln-Rice Ln-Stanford Danville(3)	
3. Circuit Name and Number		
4. Circuit Location		
	Carmans Ln, Crawford Ln, US 150	
5. Total Circuit Length (Miles)	36.21	
6. Customer Count	657	
7. Date of Last Circuit Trim	Jun-11	
8. Outage Cause (% of Total Outage Numbers)		
Animals	1.05%	
Lightning	37.55%	
High Wind	0.39%	
Equip. Failure	25.95%	
Deteriorated	0.00%	
Cars or Trucks	0.00%	
Insulation broke	0.00%	
Vegetation/Trees	6.12%	
Trees Cut Into Line	0.00%	
Equipment OL	0.00%	
Rain/ Ice	28.74%	
Cased by Others	0.19%	
9. Circuit 5 Year Average (SAIDI)	50.51842076	
10. Reporting Year (SAIDI)	154.8782344	
11. Circuit 5 Year Average (SAIFI)	38.54417635	
12. Reporting Year (SAIFI)	114.1552511	
13. List of Corrective Action, If Any, Taken or To Be Taken		

None

Circuit #	5:
-----------	----

1. Substation Name and Number	Lebanon(7)	
2. Substation Location	Marion-S. Harris St-Lebanon Miller Pike(2)	
3. Circuit Name and Number		
4. Circuit Location		
US 68,	Miller Pike, Calvery Rd, Old Calvery R	
5. Total Circuit Length (Miles)	84.29	
6. Customer Count	740	
7. Date of Last Circuit Trim	May-11	
8. Outage Cause (% of Total Outage Numbers)		
Animals	1.37%	
Lightning	12.77%	
High Wind	9.35%	
Equip. Failure	2.10%	
Deteriorated	0.00%	
Cars or Trucks	0.00%	
Insulation broke	0 00%	
Vegetation/Trees	74.41%	
Trees Cut Into Line	0.00%	
Equipment OL	0.00%	
Rain/ Ice	0.00%	
Cased by Others	0.00%	
9. Circuit 5 Year Average (SAIDI)	49.50484324	
10. Reporting Year (SAIDI)	36.05	
11. Circult 5 Year Average (SAIFI)	29.54675186	
12. Reporting Year (SAIFI)	32.75675676	
13. List of Corrective Action, if Any, Taken or To Be Taken		
2014-2017 Work Plan Actions To Be Taken:	328 (2015), 329 (2014), 330 (2017)	
New Calvary Rd-Convert 2.7 miles of 1 phase #4 ACSR distributio	n circuit to 3 phase 1/0 AAAC.	
Old Hwy 68-Convert 1.8 miles of 1 phase distribution (13 transform	mers) from 7.2 to 14.4 KV.	
Arbuckle Road-Convert .75 miles of 1 phase 1/0AAAC distribution	circuit to 3 phase 1/0 AAAC.	

Substation Name and Number Substation I wastier	Marion Industrial(12)
2. Substation Location	Marion-Industrial Dr-Lebanon
3. Circuit Name and Number	Industrial(3)
4. Circuit Location	1.1
	Lebanon-Industrial Dr
5. Total Circuit Length (Miles)	1.7
6. Customer Count	10
7. Date of Last Circuit Trim	Industrial Circuit
8. Outage Cause (% of Total Outage Numbers)	
Animals	9.11%
Lightning	42.42%
High Wind	0.00%
Equip. Failure	20.04%
Deteriorated	28.43%
Cars or Trucks	0.00%
Insulation broke	0.00%
Vegetation/Trees	0.00%
Trees Cut Into Line	0.00%
Equipment Ol	0.00%
Rain/ Ice	0.00%
Cased by Others	0.00%
9. Circuit 5 Year Average (SAIDI)	167.7
10. Reporting Year (SAIDI)	488.5
11. Circuit 5 Year Average (SAIFI)	217
12. Reporting Year (SAIFI)	534
13. List of Corrective Action, If Any, Taken or To Be Taken	
2014-2017 Work Plan Actions To Be Taken:	None

Circu	it	#7:	
-------	----	-----	--

1. Substation Name and Number	Perryville (6)
2. Substation Location	Boyle-Harrodsburg Rd-Perryville
3. Circuit Name and Number	Harrodsburg(1)
4. Circuit Location	
	US 68, Quirks Run, Bluegrass Pike
5. Total Circuit Length (Miles)	56.82
6. Customer Count	372
7. Date of Last Circuit Trim	Aug-11
8. Outage Cause (% of Total Outage Numbers)	
Animals	0.46%
Lightning	94.19%
High Wind	2.58%
Equip. Failure	0.00%
Deteriorated	0.00%
Cars or Trucks	0.00%
Insulation broke	0.00%
Vegetation/Trees	2.58%
Trees Cut Into Line	0.18%
Equipment OL	0.00%
Rain/ Ice	0.00%
Cased by Others	0 00%
9. Circuit 5 Year Average (SAIDI)	64.5120953
10. Reporting Year (SAIDI)	87.18817204
11. Circuit 5 Year Average (SAIFI)	38 85686755
12. Reporting Year (SAIFI)	56.12903226
13. List of Corrective Action, If Any, Taken or To Be Taken	
2014-2017 Work Plan Actions To Be Taken:	None

1. Substation Name and Number	Shelby City(4)
2. Substation Location	Boyle-E Knob Lick Rd-Junction City
3. Circuit Name and Number	Alum Springs(4)
4. Circuit Location	
	Aium Springs, White Oak, Hwy. 34
5. Total Circuit Length (Miles)	77.75
6. Customer Count	1073
7. Date of Last Circuit Trim	May-14
8. Outage Cause (% of Total Outage Numbers)	
Animals	32.82%
Lightning	24.56%
High Wind	5.53%
Equip. Failure	24.61%
Deteriorated	3.78%
Cars or Trucks	0.00%
insulation broke	0.04%
Vegetation/Trees	4.13%
Trees Cut Into Line	0.25%
Equipment OL	0.25%
Rain/ Ice	4.02%
Cased by Others	0.00%
O. Cirnuit & Voor Averney (SAIDI)	57.08761714
9. Circuit 5 Year Average (SAIDI)	98.71015844
10. Reporting Year (SAIDI)	79.67297301
11. Circuit 5 Year Average (SAIFI)	
12. Reporting Year (SAIFI)	100.1491146
13. List of Corrective Action, If Any, Taken or To Be Taken	247 (0040)
2014-2017 Work Plan Actions To Be Taken:	347 (2016)

Lebanon Road-Convert 1.3 miles of 1 phase 1/0AAAC distribution circuit to 3 phase 1/0 AAAC.

-	 **	-
	 	#9:

Substation Location Circuit Name and Number	Mercer-Dry Branch-Harrodsburg
3. Circuit Name and Number	
J. Chydit (fallic ally ffullipe)	Dixville(2)
4. Circuit Location	
	Rose Hill, Perryville Rd, Dixville
5. Total Circuit Length (Miles)	63,53
6. Customer Count	620
7. Date of Last Circuit Trim	Apr-11
8. Outage Cause (% of Total Outage Numbers)	
Animals	1.66%
Lightning	4.70%
High Wind	16 22%
Equip. Failure	4.64%
Deteriorated	71.17%
Cars or Trucks	0.00%
Insulation broke	0.00%
Vegetation/Trees	1.61%
Trees Cut Into Line	0.00%
Equipment OL	0.00%
Rain/ Ice	0.00%
Cased by Others	0.00%
9. Circuit 5 Year Average (SAIDI)	98.94713643
10. Reporting Year (SAIDi)	124.4822581
11. Circuit 5 Year Average (SAIFI)	52.17999952
12. Reporting Year (SAIFI)	83 61290323
13. List of Corrective Action, If Any, Taken or To Be Taken	
2014-2017 Work Plan Actions To Be Taken:	314 (2014), 315 (2014)

Mackville Road-Convert 1.3 miles of 1 phase #4ACSR distribution circuit to 3 phase 1/0 AAAC.

Johnson Road-Convert .3 miles of 1 phase #4ACSR distribution circuit to 2 phase 1/0 AAAC.

Electric Distribution Utility Annual Reliability Report

Additional pages may be attached as necessary SECTION 6: VEGETATION MANAGEMENT PLAN REVIEW

Inter-County Energy completed the first year of its 5 year vegetation management plan. Energy is closely monitoring the results of the first year of our second cycle.	Inter-County
Energy is closely monitoring the results of the first year of our second cycle.	
	i
	l
SECTION 7: UTILITY COMMENTS	
<u> </u>	
	
	